



REVISION RECORD	
ECO NO.	APPROVED BY

1. DISCONNECT POWER CORD BEFORE SERVING
2. RECOMMEND THE UNIT BE OPERATED BY DC 5V VOLTS DURING TROUBLE SHOOTING
3. COMPONENTS MARKED WITH HAVE CRITICAL CHARACTERISTICS ONLY REPLACE WITH THE COMPONENT OF THE SAME TYPE NUMBER
4. SUBJECT TO CHANGE WITHOUT NOTICE

190-938001-01

HR 405 TREVI