


lred MCX 1034USB

U1 Pin93 -Pin100 and Pin111 -Pin113 and Pin116 is GPIO

For Servo Debug 2006 02 09



- TP1 FELPFD
- TP2 TELPFD
- TP3 SBLPFD




MOTOR Input Choose

Change By 2006 02 09

| | | |
|---------|----------------|----------|
| Sanyo | R14 R25 R35 OR | R39 5.1K |
| Sony | R14 R25 R35 OR | R39 3.3K |
| Samsung | R14 R25 R35 OR | R39 8.2K |



| Internal Flash | RAS | BAS |
|---|-----|-----|
| Internal serial | 1 | 1 |
| Flash only | 1 | 0 |
| BIOS Internal Flash and Internal serial | 0 | 1 |
| Flash only | 0 | 0 |



Change Value from 10K to 1K
Change by 2006 02 09